Material Safety Data Sheet

1. Product and Company Identification

Product Name : Coatings for enamelled Copper Wire

Product Code : Polyamide Imide Varnish (YAI405 \ YAI406)

Suggested Use & Restriction : Insulating coatings for Copper Wire

Identification of Supplier : Yee Fong Chemical & Industrial Co., Ltd. Taoyuan plant / No.377, Haihu E. Rd., Lujhu Township, Taoyuan County, Taiwan

Phone Number/Tax Number : TEL : (03) 3541944 ; FAX : (03) 3541957

2. Hazards Identification

Hazard Identification : Flammable liquids Grade 2		
Corrosion / irritation of the skin Grade 2		
Serious injury /Irritation of the eyes Grade 2		
Toxic to Reproduction Grade 1		
Specific organ systematic toxicity \sim Repeated exposure Grade 2		
Aspiration hazard Grade 1		
Mark Content :		
$\land \land $		
Symbols : V V V		
Warnings: Danger		
Hazard Warning Information: Highly Flammable liquid and vapor		
Causes skin irritation		
Causes eye irritation		
May damage fertility or the unborn child		
Long-term or repeated exposure will cause organ damage		
May be fatal if swallow and enter into respiratory		
Precautionary statements : Place container in a well-ventilated place		
Away from the Inflammables - Smoking prohibited.		
If contact with the eyes, wash with plenty of water immediately and seek		
medical care		
Wear suitable protective clothing, gloves, goggles / face shields		
Other Hazards : —		

3. Component Identification Information

Hazardous Ingredients				
Name	Synonyms	Chemical	Content (%)	CAS. No.
		formula		
N-methylpyrro-lidone	NMP	C5H9NO	50~70	00872-50-4
XYLENE	DIMETHYLBENZENE MIXED XYLENE	C8H10	10~20	01330-20-7

4. First Aid Measures

First Aid Procedures Under Different Exposure:

Inhalation :

- 1. Remove pollution sources or move the Patient to fresh air.
- 2. If not breathing, apply artificial respiration or CPR immediately by trained people.
- 3. Seek medical treatment immediately.

Skin contact:

- 1. Erased or siphoning off excess chemicals Promptly.
- 2. Wash by water or soapy water for about 20 minutes immediately.
- 3. Seek medical treatment immediately.

Eye contact:

- 1. Hold eyelids immediately, rinse contaminated eyes with water for 30 minutes.
- 2. Seek medical treatment immediately.

Ingestion :

- 1. If the patient is about to lose consciousness or have lost consciousness, do not feed anything.
- 2. Rinse the mouth with water thoroughly.
- 3. Do not induce vomiting.
- 4. Seek medical treatment immediately.

The most important symptoms and hazardous effects:

Burns of respiratory tract, eyes, skin, and mucous membranes

Protection of first aid personnel : Required to wear protective equipment and then first aid in the safe zone.

Notes to a Physician : Inform the patient's symptoms and exposure pathways, provide material safety data sheets as a reference.

5. Fire Fighting Measures

Suitable Extinguishing : Dry chemical, foam, carbon dioxide

Special hazards that may be encountered when extinguishing : Skin or eye contact burns, smoke inhalation choking injuries or suffocation.

Special fire fighting procedures : Not suitable extinguishing with water, but a water spray is able to cool down the containers which exposed to fire. If there is no risk, move the container from the scene of the fire. Wear the appropriate protective masks to extinguish the fire.

Special protective equipment for fire-fighters : Fire fighters must wear Class B chemical protective suits and air respirators (If necessary, plus anti-Flash aluminum approvals jacket).

6. Accidental Release Measures

Personal precautions :

- 1. Restrict access until the contaminated area is completely clean.
- 2. Confirming that the person who is responsible for the clean-up is well-trained.
- 3. Wear appropriate personal protective equipment (PPE).

Environmental Considerations :

- 1. Ventilate the leakage area.
- 2. Remove all ignition sources.
- 3. Notify the environmental protection unit.

Clean-up methods :

- 1. Use rag or paper towel to absorb when small amount of leakage of liquid. Use dry sand or similar material to absorb when massive fluid leaks.
- 2. Avoid inflow to sewer or ditch •

7. Handling and Storage Methods

Handling :

- 1. Keep away from heat, ignition sources and incompatible materials.
- 2. Use non-sparking, qualified explosion-proof equipment and electrical safety system.
- 3. Posted "Smoking and lighting fires strictly prohibited "as warning signs.
- 4. Empty barrels, containers and pipes residue to clean before welding or cutting.
- 5. Operating in a well-ventilated area and away from storage area.
- 6. Do not use with incompatible materials (such as strong oxidant) to reduce the risk of fire and explosion.
- 7. The containers should be labeled. Keep tightly closed when not in use and avoid damage.

Storage :

- 1. Store in a cool, dry, well-ventilated, and direct sunlight place.
- 2. Workspace and storage areas shall be separated to avoid a lot of storage in the indoor.
- 3. Storage should be capped tightly closed to prevent solvent escaping.

8. Exposure Prevention Measures

Engineering controls :

- 1. Operate under completely explosion-proof equipment.
- 2. Supply sufficient fresh air to supplement the pull out of the air by the exhaust system.
- 3. Emissions required to take appropriate measures on the environment.

Control parameters:

Average allowable concentration of eight hours time weighted / Average allowable concentration of short period / Maximum allowable concentration / Biological indicators:

Hazardous	Average	Average	Maximum	Biological
substances	allowable	allowable	allowable	indicators
	concentration of	concentration	concentration	
	eight hours time	of short period		
	weighted			
N-methylpyrro- lidone	100ppm			
Xylene	100ppm	125ppm		containing In urine of kima uric acid 1.5g A / 1g creatinine after work

Personal protective equipment :

Eyes : Poorly ventilated chemical safety goggles, full-face helmet.

Breath :

- 1. Organic vapor canister and dust droplet filter respiratory protection.
- 2. Whole face self-priming protection
- 3. Air-supplying respirator

Gloves : Chemical protective gloves made from polyvinyl alcohol is preferred.

Others : Rubber coveralls protective clothing, work boots, and emergency irrigator.

Hygienic measures :

1. Food, clothing and the skin should be taken to avoid contamination.

2. Workplace non-smoking or diet.

3. Wash hands thoroughly after handling this substance.

4. Maintain a clean work

9. Physical and Chemical Properties

Physical state: Liquid	Shape: Viscous liquid
Color:Light coffee	Smell: Special smell
рН: —	Boiling point / Boiling range : $N : 76 \sim 82^{\circ}C$, X : 138°C
Decomposition temperature: —	Flash Point : N : -21° > X : 38° Test methods : Closed Cup
Ignition temperature : —	Explosion limits : Upper explosive limit: X: 7% N:- Lower explosive limit: X:1.0% N:-
Vapor pressure : $P : - Y : 8$	Vapor Density : $N : 2.9 , X : 3.7$
Density : N : 0.8~0.8188 , X : 0.86	Solubility : N : Soluble in water, ether X : Slightly soluble
Octanol / water partition coefficient (log/kow) : —	Evaporation rate $:$ –

10. Stability and Reactivity

Stability : Stable under normal conditions		
Hazardous reactions under Special Conditions : Fire		
Conditions to avoid : Contact with the source of fire		
Substances to be avoided : Strong oxidizing agent, alkali, heat		
Hazardous Decomposition Products : Nitrogen oxides, carbon oxides		

11. Toxicity Data

Routes of exposure : Inhalation, skin, eyes, ingestion.

NMP Acute toxicity :

Inhalation :

- 1. May cause irritation of respiratory tract and accompanied by coughing, choking, pain, and possibly burns of mucous membranes.
- 2. The serious situation likely to immediately develop into pulmonary edema, or incubation period is usually 5 to 72 hours; symptoms may include chest tight, dyspnea, frothy sputum, hair rickets and dizziness.
- 3. The discovery of the body may include low blood pressure, weakness, rapid pulse and wet blisters.
- 4. The most severe cases can be fatal.

Skin :

- 1. Direct contact may cause severe pain, burns, and dyed brown.
- 2. Corroded area may become soft, gelatinous and necrotic. Damage of skin tissue may be deep.

Eyes :

- 1. Direct contact may cause pain and burns.
- 2. Edema epithelial destruction corneal opacity and iritis.
- 3. Severe burns, the whole picture of the damage may not be immediately apparent. Complications may include persistent edema, corneal vasculature formation and scarring, permanent opacity, staphyloma, cataract and blindness

Ingestion:

1. May cause immediate pain and the peristomial burns and mucosal corrosion, the first white

edema and ulceration, blistering and then turn brown.

- 2. Possible flow of saliva and swallowing and speaking difficulties.
- 3. Even if there is no obvious burns the esophagus and stomach may also burns, vomiting and diarrhea.Epiglottis edema may lead to respiratory distress and possible suffocation.
- 4. May occur in blood pressure is too low to cause shock, weakness, rapid pulse, shallow breathing, clammy skin; circulatory collapse may.
- 5. Can continue to occur, if there is no regulation will result in kidney failure.
- 6. Serious gastric perforation, followed by esophageal perforation. After that may occur peritonitis accompanied by fever and abdominal stiffness.
- 7. May occur to the esophagus, stomach and pyloric stenosis in the initial few weeks, but may also be delayed for several months or even several years.
- 8. Asphyxia, circulatory collapse or reverse absorption of this substance, may cause death in a short time or within minutes. Other possible cause of death may be for perforated complications, pneumonia or esophagus, stomach and pyloric stenosis.

Xylene Acute toxicity :

Inhalation :

- 1. Brief exposure to 200ppm concentration can irritate the nose and throat.
- 2. Exposed to 700ppm concentration, can cause nausea and vomiting.
- 3. Exposure to high concentrations can cause incoordination, loss of consciousness, liver kidney damage, respiratory failure and death.

Skin:

- 1. Long-term exposure can cause dermatitis.
- 2. Vapors may irritate the skin.
- Eyes : Vapor and liquid can irritate the eyes.

12. Ecological Information

NMP Ecotoxicity :

Lc₅₀(Fish):36500mg/L/96H(Oncorhynchus mykiss) Ec₅₀(Aquatic Invertebrates):2080µg/L/48H(Daphnia pulex)

Xylene Ecotoxicity:

Lc₅₀(Fish):13.5mg/L/96H(Lepomis macrochairus)

Persistence and degradability:

- 1. Release into water, will be eliminated by evaporation.
- 2. Release into the air, with the hydrogen radical reactions quickly eliminated.
- 3. Test with standard biodegradable, will be decomposed by ditch activity pollution.
- Half-life (air): 2.6 ~ 44 hours
- Half-life (water surface): 168 to 672 hours
- Half-life (groundwater): 336 to 8640 hours
- Half-life (soil): 168 to 672 hours

Bioaccumulation :

The majority is broken down in the liver and excreted in the urine, a small portion is discharged by the breathing; No food chain concentrated or accumulated.

The liquidity of the soil :

Would evaporate and seep into the soil.

Other adverse effects: -

13. Waste Disposal Method

Waste Disposal Method :

Refer to Toxic Chemical Substances Control Act, the industrial waste storage, clearance and processing methods and related laws, prohibit indiscriminate dumping.

14. Transport Information

UN number : UN1992

International shipping name : Coating

Hazard classification of transportation: The third category of flammability and the sixth category of toxic substances.

Packing Group : –

Marine pollutant (Yes/No) : No

Special delivery methods and precautions : –

15. Regulatory Information

Applicable laws and regulations :	
1. Labor safety and sanitation rules	4. General rules of the dangerous and harmful materials
2. Organic solvent poisoning prevention rules	5. Standards of permissible concentration of harmful substances in the working environment
3. The rules of the traffic safety	6. Storage of industrial waste clean-up processing methods and facilities standards

16. Other Information

16. Other	r Information		
Reference	 Industrial Technology Research Institute: The Center For Safety & Health Tecnology. MSDS. Council Of Labor Affairs Executive Yuan GHS Information website http://ghs.cla.gov.tw GHS Mixture Expert System 		
Prepared Unit	Name : Yee Fong Chemical & Industrial Co., Ltd. Taoyuan plant Address / Phone : No.377, Haihu E. Rd., Lujhu Township, Taoyuan County, Taiwan TEL : 03-3541944		
Preparers	Titles : Process Engineer	Name (Signature) : Ming-Hong, Huang	
Tabulation Date	2012/1/4		

The above information is produced by the Yee Fong Chemical Industry Co., Ltd. by referring CLA information. All the information here is for reference only. Users should make application needs to determine its availability.